

2007 Brooder Barn



Exterior View – S End



02/05/2008

Exterior View – W Side



02/05/2008

Exterior View – E Side




02/05/2008

Interior Side Wall


02/05/2008

Plasson Bell Waterer



02/05/2008

Bell/Screen/Drain



02/05/2008

Raised Equipment



02/05/2008

Enter/Exit Garage Door



02/05/2008

Aerotech Ventilation




02/05/2008

Temperature Probe



02/05/2008

Inlet Air Shutter



02/05/2008

Ventilation Fans



02/05/2008

Variable/Constant



02/05/2008

Circulation Fan



02/05/2008

Inlet Shutter



02/05/2008

Vent Tube



02/05/2008

Day One Chicks



Nipple Line/Canopy/Attraction Light



Sierra Canopys



BR Nipple System w/Activator





Activator



Labor Comparison – Yearly Hours

	Old	New
Washing	24	8
Cleaning	48	20
Movements	64	48
Chick Care(84days)	210	84
LP	same	
Electrical	?	
Feed	?	

Chick Loss Comparison

Year	Chicks	% Death Loss
2005	35160	.028 – 3 wk
2006	35861	.056 – 3 wk
2007	36859	.053 – 3 wk